### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 99.28

## WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-016421 Address: 333 Burma Road **Date Inspected:** 19-Aug-2010

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC) Chanxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes N/A No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component: OBG Segments 11CW** 

### **Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance Inspector (QA), Vibin Kumar Selvanayaham, was present during the times noted above for observations relative to the work being performed.

Magnetic Particle Testing (MT) - Document No's: 006413

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The members are identified as OBG 11CW. The weld designations reviewed are as follows:

- 1. DP186-001-011~057
- 2. DP213-001-011~057
- 3. DP240-001-011~057
- 4. DP267-001-011~057
- 5. DP294-001-007~035
- 6. SSD14-PP104-004

Magnetic Particle Testing (MT) - Document No's: 006437

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The members are identified as OBG LD Lift 13. The weld designations reviewed are as follows:

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

- 1. LD3036-001-005, 006, 007, 008, 009, 010, 067, 068, 069, 070
- 2. LD3032-001-006, 007, 008, 009, 010, 011

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

## **Summary of Conversations:**

Only general conversation was held between QA and QC concerning this project.

### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact, who represents the Office of Structural Materials for your project.

Inspected By:	Kumar, Vibin	Quality Assurance Inspector
Reviewed By:	McClendon, Timothy	QA Reviewer